


Double check valves for YEAT model









Part nº	R1	Max. flow (l/min)	Max. Press. (bar)	Pilot ratio
YAEAT-D H	3/8" BSP	40	315	3:1

Tightening torque of the rods that join the valves must be 20Nm

The information gathered in this technical documentation (Catalogue) has an informative character and can be modified without previous notice. DICSA will not accept any type of responsibility resulting from an inappropriate use of the product, except the ones related to manufacturing defects.