Joystick on control valve for 2 spools







Part nº	Control valve
801120	FM55 / BM30 / BM40
801291	BM70 / FM85

TO FIT THIS, YOU WILL ALSO NEED TO REPLACE THE SPOOLS IN THE MANIFOLD; THESE ARE SPECIAL PARTS AND THE STANDARD FACTORY-FITTED ONES ARE NOT SUITABLE

The information gathered in this technical documentation (Catalogue) has an informative character and can be modified without previous notice. DICSA will not accept any type of responsibility resulting from an inappropriate use of the product, except the ones related to manufacturing defects.