




Bore (mm)/Camisa (mm)	10	16	20	25	32
Working pressure/Presión de trabajo (bar)	1-7		0.5-7		
Guaranteed pressure/Presión garantizada (bar)	10.5				
Temperatura de trabajo/Working temperature (°C)	5-60°C				

Part nº	Stroke (mm)	A	B	C	D	E	F	G	H	I
CNDEM1010	10	72	55	30	10	46	17	35	2-M4x0,7	36.5
CNDEM1020	20	72	55	30	20	46	17	35	2-M4x0,7	36.5
CNDEM1025	25	72	55	30	25	46	17	35	2-M4x0,7	36.5
CNDEM1030	30	72	55	40	30	46	17	35	2-M4x0,7	36.5
CNDEM1040	40	72	55	40	40	46	17	35	2-M4x0,7	36.5
CNDEM1050	50	72	55	40	50	46	17	35	2-M4x0,7	36.5
CNDEM1060	60	72	55	50	60	46	17	35	2-M4x0,7	36.5
CNDEM1070	70	72	55	50	70	46	17	35	2-M4x0,7	36.5
CNDEM1075	75	72	55	50	75	46	17	35	2-M4x0,7	36.5
CNDEM1080	80	72	55	50	80	46	17	35	2-M4x0,7	36.5
CNDEM1090	90	72	55	60	90	46	17	35	2-M4x0,7	36.5
CNDEM10100	100	72	55	60	100	46	17	35	2-M4x0,7	36.5