




Recommended oil: SAE-90

| Part n°            | Details          | Exit            | Relation |
|--------------------|------------------|-----------------|----------|
| MULTIPLI.F-II-1    | F.II             | Hembra / Female | 1:2      |
| MULTIPLI.F-II      | F.II             | Hembra / Female | 1 : 3,4  |
| MULTIPLI.FII-MACHO | F.II             | Macho / Male    | 1:3,8    |
| MULTIPLI.FIII-1    | F-III / FII-FIII | Hembra / Female | 1:2      |

The information gathered in this technical documentation (Catalogue) has an informative character and can be modified without previous notice. DICSQ will not accept any type of responsibility resulting from an inappropriate use of the product, except the ones related to manufacturing defects.

Over gears without splin.half-coup.

| Part n°               | Details          | Exit            | Relation |
|-----------------------|------------------|-----------------|----------|
| MULTIPLI.FIII         | F-III / FII-FIII | Hembra / Female | 1:3,4    |
| MULTIPLI.FIII-MACHO-1 | F-III / FII-FIII | Macho / Male    | 1:2      |
| MULTIPLI.FIII-MACHO   | F-III / FII-FIII | Macho / Male    | 1:3,8    |

F II: Max 10KW.  
F III: Max 20 KW.