
Plug for relief valve cavity







Part nº	Control valve
832018	FM35
832010	FM55 / BM30 / BM40
832012	FM85/ BM70

The information gathered in this technical documentation (Catalogue) has an informative character and can be modified without previous notice. DICSA will not accept any type of responsibility resulting from an inappropriate use of the product, except the ones related to manufacturing defects.