


Pressure relief valve





MC0... H






MCX... H







MCX....for: Blocenx

Part nº	R1	Reg. rate (bar)
MC031 H	3/4" -16 UNF	10-60
MC032 H	3/4" -16 UNF	50-150
MC051 H	3/4" -16 UNF	100-200
MCX031 H	3/4" -16 UNF	10-60
MCX032 H	3/4" -16 UNF	50-150
MCX051 H	3/4" -16 UNF	100-200
MCX062 H	3/4" -16 UNF	150-250

The information gathered in this technical documentation (Catalogue) has an informative character and can be modified without previous notice. DICSA will not accept any type of responsibility resulting from an inappropriate use of the product, except the ones related to manufacturing defects.