







T=1/2" BSP
P2/C=3/8" BSP
P1/M=1/4" BSP

P1=10L/MIN
P2=25L/MIN
C=30L/MIN

Part nº	WORK PRESSURE (bar)
FPMSE PD-P-3/8 20-10	20-100, 50-220
FPMSE PD-P-3/8 35-20	50-220, 80-350