
Support drive without splined half-coupling



Part nº	Details	Axial charge	Exit
SOPORTE F.I	F.I	100	Cylindrical shaft 18 mm
SOPORTE F.I CONICO	F.I	100	Tapered shaft 1:8
SOPORTE F.II	F.II	170	Cylindrical shaft 18 mm
SOPORTE F.II CONICO	F.II	170	Tapered shaft 1:8
SOPORTE F.III	F.III	320	Cylindrical shaft 24 mm
SOPORTE F.III CONICO	F.III	320	Tapered shaft 1:8

The information gathered in this technical documentation (Catalogue) has an informative character and can be modified without previous notice. DICSA will not accept any type of responsibility resulting from an inappropriate use of the product, except the ones related to manufacturing defects.

Support drive without splined half-coupling

Part nº	Details	Axial charge	Exit

***** Review attached PDF*****

The information gathered in this technical documentation (Catalogue) has an informative character and can be modified without previous notice. DICSA will not accept any type of responsibility resulting from an inappropriate use of the product, except the ones related to manufacturing defects.